WATER WELLS

Specialist in : Ground Water Exploration, Development, Management and Rejuvenation

GEOLOGICAL - GEOHYDROLOGICAL - GEOPHYSICAL REPORT

V. APRAMEYA MURTHY, B.Sc (HONS), M.Sc
Ex-Officio RDPR, Department
744, 7th A Cross, A Sector
Yelahanka New Town, Bangalore - 560 064.

MOB : 94484 19262
RES : 080-28561744

Date :

1. Name :	AEE Kodigehally Sub-Dv" Byatarayanapura BBMP Yelahanka Zone Ward 7.		
2. Address : Survey No.:	Near Osteem mall crematorium	Taluk :	Bangalore
		Dist :	Bangalore
3. Topography of the area.		Low plain Terrain	
4. Geology of the area.		Granitic	
5. Geohydrological condition of the area		Moderate	
6. Survey conducted for	A. Type of Area	Agriland / Site / Layout /	
	B. Purpose	Irrigation / Domestic / Water Supply	
7. Method of Survey Employed :		Geological - Geophysical - Geohydrological	
8. RECOMMENDATION	A. Type of well	$6\frac{1}{2}$" Dia Bore Well	
	B. Location		
	C. Depth	1200 ft	
	D. Probable casing	100 to 120 ft	
9. YIELD EXPECTED*		upto 2"	
10. SPECIAL RECOMMENDATION IF ANY		Outer P.V.C. Casing is Required	

*Conditions Apply.

For WATER WELLS

Geologist

A.P.M.Y.N.D
AE(Ast)

|| Sri Veeranna Gowda Prasanna ||



ಶ್ರೀ ಲಕ್ಷ್ಮೀ ಬೋರ್‌ವೆಲ್ಸ್ ಮತ್ತು ಅರ್ಥ್‌ಮೂವರ್ಸ್

SRI LAKSHMI BOREWELLS & EARTH MOVERS

Dealers in : All Kinds of Irrigation & Domestic Pumps

Fast Drilling & Re-Drilling Contractors

Opp. Big Market, Sahakaranagar, Airport Road, Byatarayanapura, Bangalore - 92.

Mob. : 9845404291

Ref. :

Date :

To.

The Assistant Executive Engineer
Kodigehalli subdivision.
BBMP. BJR.

The borewell sinking at Crematorium near Osteen wall yielded no water. (Failed)

Thanking you.